BOSE MCKINNEY & EVANS LLP

RECEIVED CUSTOMER NUMBER 2526

DEC 3 1 2003

CHNOLOGY CENTER R3700

2700 First Indiana Plaza 135 N rth Pennsylvania Str et Indianap IIs, Indiana 46204

PATENT APPLICATION

Applicant:

Eckstein et al.

Serial No.:

10/085,966

Filing Date:

February 28, 2002

Title:

HYDRAULIC CONTROL APPARATUS

FOR A HOSPITAL BED

Group:

3754

Examiner:

Keasel, E.

Attorney Docket No.:

8266-0823

MAIL STOP AF COMMISSIONER FOR PATENTS P. O. BOX 1450 ALEXANDRIA, VA 22313-1450

Dear Sir:

Transmitted herewith is a response in the above-identified application:

The fee has been calculated as shown below:

Ø	Certificate Under 37 C.F.R. 1.8(a)				
	I hereby certify that this paper or fee is being deposited with the United States Postal Service as first class mail in an envelope addressed to: MAIL STOP AF, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.				
TUS	On <u>December 22, 2003</u>				
. –	D. Cwiklinski				

December 22 2003

CLAIMS AS AMENDED						
	CLAIMS REMAINING AFTER AMENDMENT	HIGHEST NO. PREVIOUSLY PAID FOR	NUMBER EXTRA	RATE	FEE	
TOTAL CLAIMS (37 C.F.R. 1.16(c))	13	22	0	\$18	\$0	
INDEPENDENT CLAIMS (37 C.F.R. 1.16(b))	3	5	0	\$86	\$0	
If applicant has small entity status under 37 C.F.R 1.9 and 1.27, then divide total fee by 2, and enter amount here. SMALL ENTITY TOTAL					\$0	
TOTAL FEE FOR ADDITIONAL CLAIMS						

	An Extension of Time for month(s) is hereby requested under 37 C.F.R. 1.136(a). The required fee for filing this extension is:	
	Information Disclosure Statement	
	\$0	

___ A check in the amount of \$_____ to cover the total fee for this amendment is attached.

The Commissioner is hereby authorized to charge any additional filing fees under 37 C.F.R. 1.16 or processing fees under 37 C.F.R. 1.17 which may be required during the prosecution of this application, or credit of any overpayment, to Bose McKinney & Evans LLP's Deposit Account No. 02-3223. A duplicate copy of this sheet is enclosed.

Attorney of Record

Printed Name: Ryan C. Barker

Registration No.: 47,405